

TO BE FILLED BY THE INSPECTING OFFICER

(Assistant Engineer)

Name of the school : HOLY CROSS CONVENT SCHOOL, Vettilappara
1. Name of the Officer : Jameela Mumtaz, P
2. Location : Vettilappara
3. Period for the Certificate is issued : 2024-25
4. Types of building : Measurement of building - Old Building

Ground Floor

- 1) 5.80 x 5.80 x 3.30 m
- 2) 5.80 x 5.80 x 3.30 m
- 3) 2.30 x 6.20 x 3.30 m
- 4) 3.80 x 5.80 x 3.30 m
- 5) 5.80 x 5.80 x 2.20 m
- 6) 2.30 x 5.80 x 2.20 m
- 7) 3.00 x 5.80 x 2.20 m
- 8) 2.00 m wide verandah

First Floor

- 1) 6.20 x 5.60 x 3.00 m
- 2) 2.00 x 5.60 x 3.40 m
- 3) 6.20 x 6.20 x 3.00 m
- 4) 6.20 x 6.20 x 3.40 m
- 5) 6.00 x 6.20 x 3.40 m
- 6) 6.00 x 6.20 x 3.40 m
- 7) 2.00 m wide verandah

Second floor

- 1) 8.40 x 5.60 x 3.00 m
- 2) 6.20 x 6.20 x 3.00 m
- 3) 6.20 x 6.20 x 3.00 m
- 4) 12.20 x 6.20 x 3.00 m
- 5) 2.00 m wide verandah

Measurement of building - New building

Basement

- 1) 9.80 x 6.50 x 3.60 m- (Science Lab)

Ground Floor

- 1) 6.60x6.40x3.60m – (4 class rooms)
- 2) 13.50x6.50x3.60m- (Computer Lab)
- 3) 2.50 m Wide verandah

First Floor

- 1) 6.60 x 6.40 x 3.60m-(6 CR)
- 2) 13.50 x 6.40 x 3.60m-(AV Room)
- 3) 2.50 m Wide verandah

Second Floor

- 1) 13.50 x 6.40 x 3.60m (Library)
- 2) 6.60 x 6.40 x 3.60m (Class room)
- 3) 48.00 x 9.00 x 3.60m (Hall)

5. Nature of defect if any :No
 - a) Foundation and basement : Nil
 - b) Superstructure : Nil
 - c) Doors and windows : Nil
 - d) Wood work wrought and put up : Nil
 - e) Roof : Nil
 - f) Flooring : Nil
 - g) Miscellaneous(Cracks if any) : Nil
6. Any Major defects notices which will Render the building unsafe if any Manner : No at the time of inspection.
7. Whether maintenance work have been Done properly : Yes
8. Whether the structure is sound or Not for conducting Classes : Yes sound for conducting classes under normal weather and wind conditions.

Note: 1.The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.

2. Any additional observation if deemed necessary for the certificate may be furnished separately with the Certificate.

Certified that the school was inspected by me on 12/09/2024 and found to be fit to conduct classes for the period for the reason stated above.

Conditions:

1. Since the built-up area of this building is more than that of the assessment register of Grama Panchayath, It should be regularized within six months in accordance with the law.
2. This fitness certificate is provisionally issued in this year only on basis of previous years fitness certificate.

Place: Therattammal
Date : 12-09-2024



Signature

JAMEELA MUMTAZ. P
ASSISTANT ENGINEER
LID & EW SECTION
URANGATTIRI GRAMA PANCHAYATH
PEN: 448419