

TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer)

Name of the school : HOLY CROSS CONVENT SCHOOL, Vettilappara
1. Name of the Officer : Jameela Mumtaz. P
2. Location : Vettilappara
3. Period for the Certificate is issued : 2020-21
4. Types of building : Measurement of building

Ground Floor

- 1) 5.80 x 5.80 x 3.30 m
- 2) 5.80 x 5.80 x 3.30 m
- 3) 2.30 x 6.20 x 3.30 m
- 4) 3.80 x 5.80 x 3.30 m
- 5) 5.80 x 5.80 x 2.20 m
- 6) 2.30 x 5.80 x 2.20 m
- 7) 3.00 x 5.80 x 2.20 m
- 8) 2.00 m wide verandah

First Floor

- 1) 6.20 x 5.60 x 3.00 m
- 2) 2.00 x 5.60 x 3.40 m
- 3) 6.20 x 6.20 x 3.00 m
- 4) 6.20 x 6.20 x 3.40 m
- 5) 6.00 x 6.20 x 3.40 m
- 6) 6.00 x 6.20 x 3.40 m
- 7) 2.00 m wide verandah

Second floor

- 1) 8.40 x 5.60 x 3.00 m
- 2) 6.20 x 6.20 x 3.00 m
- 3) 6.20 x 6.20 x 3.00 m
- 4) 12.20 x 6.20 x 3.00 m
- 5) 2.00 m wide verandah

Basement Science Lab

- 1) 9.80 x 6.50 x 3.60 m


Ground Floor – Class rooms

- 1) 6.60 x 6.40 x 3.60m – 4nos class rooms
- 2) 13.50 x 6.50 x 3.60m- Compute
- 3) 2.50 m Wide verandah

Manager
Holy Cross Convent School
Vettilappara
Malappuram (Dt), Pin-673639


Principal

Holy Cross Convent School
Vettilappara, Malappuram


Manager
Holy Cross Convent School
Vettilappara
Malappuram (Dt), Pin-673639

First Floor

- 1) 6.60 x 6.40 x 3.60m-6 nos class room
- 2) 13.50 x 6.40 x 3.60m (AU Room)
- 3) 2.50 m wide verandah

Second Floor

- 1) 13.50 x 6.40 x 3.60m (Library)
- 2) 6.60 x 6.40 x 3.60m (Class Room)
- 3) 48.00 x 9.00 x 3.60m (Hall)

5. Nature of defect if any : No
 - a) Foundation and basement : Nil
 - b) Superstructure : Nil
 - c) Doors and windows : Nil
 - d) Wood work wrought and put up : Nil
 - e) Roof : Nil
 - f) Flooring : Nil
 - g) Miscellaneous(Cracks if any) : Nil
6. Any Major defects notices which will Render the building unsafe if any Manner : No at the time of inspection.
7. Whether maintenance work have been Done properly : Yes
8. Whether the structure is sound or Not for conducting Classes : Yes ,sound for conducting classes under normal

Weather and wind condition

Note: 1.The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.

2. Any additional observation if deemed necessary for the certificate may be Furnished separately with the Certificate.

Certified that the school was inspected by me on 23/02/2021 and found to be fit to conduct classes for the period for the reason stated above.



Principal

Holy Cross Convent School
Vettilappara, Malappuram



Manager

Holy Cross Convent School
Vettilappara
Malappuram (Dt), Pin-673639

Place : Therattammal
Date : 27/02/21


Manager
Holy Cross Convent School
Vettilappara
Malappuram (Dt), Pin-673639




ASSISTANT ENGINEER
Local Self Govt. Department
Urangattiri Grama Panchayath